



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER

Executive Director

JOHN R. BAZA

Division Director

### Inspection Report

### Minerals Regulatory Program

Report Date: September 29, 2006

Supervisor

*[Signature]*

Mine Name: Quail 45

Operator Name: Color Country Rock

Preston Hafen

115 South Main

Veyo, Utah 84782

Permit number: S/053/066

Date: September 13, 2006

Time: 10:15 AM

Inspector(s): Doug Jensen

Other Participants: None

Mine Status: Inactive

Weather: Clear, warm

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated

Comment

Enforcement

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Inspected the site to observe whether any reclamation had been initiated.

#### Directions to Site:

See previous inspection memo.

#### Inspection Summary:

The BLM had notified the operator that because there had been no bond filed, the site should be reclaimed. As of the date of my inspection, no reclamation has been initiated. Pictures of the site were taken and are included in this report.

#### Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature

*[Signature: Doug Jensen]*

Date:

*9/28/06*

dj:pb

cc:

Color Country Rock

Russ Schreiner, BLM, St George FO UTU-78928

O:\M053-Washington\S0530066-Quail45\inspection\09132006insp.doc





09.13

09.13.2006 10:52